

## **CHANGE HISTORY for**

- ✓ **AVIC-F20BT**
- ✓ **AVIC-F920BT**
- ✓ **AVIC-F9210BT**
- ✓ **AVIC-F9220BT**

### **Ver 2.00300**

The new firmware fixes the following issues:

- ✓ Contacts are transferred backwards
- ✓ Voice Recognition / BT Activation Process
- ✓ Unit switches off when USB is connected
- ✓ Incorrect Spanish translation for BT message "Connection successful"